




Knelpunten en opgaven



Huidig profiel



fietsparkerenlangs gevel, voetpad?



fietsparkeren op hoeken zijstraten



fietsparken op hoek da costa kade



tamelijk breed profiel, stenig, paar bomen op hoeken



stoep westzijde bij da costa school weinig gebruikt



eindblok hoek da costa kade stenig en doods



Eerste ideeën



groene gevels, groene slingers en da costa school op groene voet




klimzuilen rond lichtmasten

?


effect?
verrommeling?

Sleutel ligt op structuurniveau

huidige positie in verkeerssysteem: 2-richtingen niet nodig...



je kan terug naar 1-richting, keerlus blijft: ruimte voor groenstrook



A perspective view of a residential street. On the right is a two-story brick building with large windows and a black door. A red car is parked in the foreground on the right. The road is paved with cobblestones and has white diagonal markings. A landscaped area with a low brick wall, trees, and colorful flowers runs along the side of the road. A tall street lamp stands in the landscaped area. White silhouettes of people are overlaid on the scene: two on the left sidewalk, one near the brick wall, and two on the right sidewalk near the brick building.

langsparkeren

loper in (nieuwe) bestrating
ref: Voorsterbeeklaan

gevelgroen